Christian Chapel Church Church and Orange Streets Port Gibson Claiborne County Mississippi HABS No. MS-203

HABS MISS, 11-POGIB,

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
Department of the Interior
Washington, D.C. 20240

Form 10-920 (June 1983)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HABS MISS, 11-POGIB

December 1984

ARCHITECTURAL DATA FORM

ATE	COUNTY	COUNTY		TOWN OR VICINITY	
MISSISSIPPI	CLAIBORNE	CLAIBORNE		PORT GIBSON	
HISTORIC NAME OF STRUCTURE (INCLUOE SOURCE FOR NAME)				HABS NO.	
CHRISTIAN CHAPEL CHURCH				MS-203	
SECONDARY OR COMMON NAMES OF STRUCTURE					
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)					
Church and Orange Streets					
DATE OF CONSTRUCTION (INCLUDE SOURCE)		ARCHITECT(S) (INCLUOE SOURCE)			
1846-1847 , Demolished May, 1972.		Unknown			
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) The Christian Chapel					
Church was a simple, good example of vernacular ecclesiastical architecture in Mississippi.					
The church side was originally owned by Joseph Moore, son-in-law of Samuel Gibson, founder of					
Port Gibson, later by the Trustees of the Christian Church. December 18, 1845, (Claiborne Co- unty Deed Book X, p 358).					
STYLE (IF APPROPRIATE) The church is an example of vernacular architecture in which simplified					
Greek REvival motifs were employed.					
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) The foundations were of brick, the load-bearing masonry walls were of brick, laid in common bond and stuccoed on the facade and					
side elevations. (Originally the building was left unstucceed.)					
HAPE AND DIMENSIONS OF STRUCTURE (SKETCHEO FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)					
rne rectangular, one-story building numbered three bays on the principal facade. The building					
measured 41' by 56'.					
EXTERIOR FEATURES OF NOTE The facade was divided into five unequal sections which were defined by brick pilasters, without capital or bases, supporting an entablature-like lintel. The					
gabled roof was covered with green asbestos sheeting. The simple stucco moldings, which de-					
corated the cornice of the pediment became the uppermost member of the entablature on the side					
elevations. A square pedestal with corner pilasters and a full entablature supported a simpl					
octagonal steeple. The entrance doors were double-leaf below a paneled and glazed transom.					
There were four, paired windows on each side with two-over-two glazing.					
TAMED TOD HEATHING OF MORE	m1. C11		1 (-1		
INTERIOR FEATURES OF NOTE The floor plan consisted of a nave and three, small rooms (class-room, office and restroom) in the rear addition. The floor was laid in narrow-width boarding.					
The walls were yellow plaster. Dark stained, beaded paneling stood behind the pulpit.					
The ceiling consisted of dark paneling set in a herringbone pattern with a dividing beam					
enriched with a large-scale patera.					
OTHER INFORMATION AS APPROPRIATE					
The church was set a few feet back from the sidewalk which ran along Church Street.					
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)					
Lississippi Department of ARchives and History. Statewide Survey File. Claiborne County.					
hurch: Christain Chapel. Project Coordinated by the Mississippi Department of Archives					
and History, Elbert R. Hilli	ard, Director. D	ata compiled by V	Villiam C Alle	n,Arch. Historian.	
COMPILER, AFFILIATION			DA	TE	

Marion K Schlefer, Historic American Buildings Survey